



# Carton Packer


## CX-50T

Power supply  
380V ± 10%/50Hz, 9.0KW  
(Three-phase four-wire system)  
Air pressure 3-6g/cm<sup>2</sup>  
Working speed 50 cases/min




## CX-100T

Power supply  
380V ± 10%/50Hz, 9.0KW  
(Three-phase four-wire system)  
Air pressure 3-6g/cm<sup>2</sup>  
Working speed 100 cases/min




## CX-20T

Power  
380V ± 10%/50Hz, 2KW  
(Three-phase four-wire system)  
Air pressure  
4-7g/cm<sup>2</sup>  
Working speed  
15 cases/min




## CX-35T

Power  
380V ± 10%/50Hz, 9.0KW  
(Three-phase four-wire system)  
Air pressure  
3-6g/cm<sup>2</sup>  
Working speed  
35 cases/min



## ZX-10T

Power  
380V ± 10%/50Hz, 2KW  
(Three-phase four-wire system)  
Air pressure  
4-7g/cm<sup>2</sup>  
Working speed  
10 cases/min




## CX-35T

Power  
380V ± 10%/50Hz, 9.0KW  
(Three-phase four-wire system)  
Air pressure  
3-6g/cm<sup>2</sup>  
Working speed  
35 cases/min



## ZX-15T

Power  
380V ± 10%/50Hz, 12KW  
(Three-phase four-wire system)  
Air pressure  
4-8kg/cm<sup>2</sup>  
Working speed  
15 cases/min




## ZX-10T

Power  
380V ± 10%/50Hz, 2KW  
(Three-phase four-wire system)  
Air pressure  
4-7g/cm<sup>2</sup>  
Working speed  
10 cases/min





### ZX-20T

Power  
380V ± 10%/50Hz, 2KW  
(Three-phase four-wire system)  
Air pressure  
4-7g/cm<sup>2</sup>  
Working speed  
20 cases/min




### ZX-60T/70T

Power  
380V ± 10%/50Hz, 18.8KW  
(Three-phase four-wire system)  
Air pressure  
4-6kg/cm<sup>2</sup>  
Working speed  
60-70 cases/min



### ZX-30T

Power  
380V ± 10%/50Hz, 11.5KW  
(Three-phase four-wire system)  
Air pressure  
4-6kg/cm<sup>2</sup>  
Working speed  
30 cases/min



### ZX-50T

Power  
380V ± 10%/50Hz, 11.5KW  
(Three-phase four-wire system)  
Air pressure  
4-6kg/cm<sup>2</sup>  
Working speed  
50 cases/min

